

Maintenance statement.**Date:** 2007-03-09

Aircraft:	Piper Navajo		
Registration:	PH-OAL	Serial nr:	31-7812037
Airframe Time:	5038.23	Cycles:	N/a
Engine 1 time:	1749.31	Prop time:	129.55
Engine 2 time:	1640.06	Prop time:	164.06
Work order:	2007 0023	Scoop of work:	1000H INSPECTION + BVL ref. rectification repair card 1,2,3,4,5,6,7,8,9,10

1

- **Sb 388 c.a.d. 2005-023 uitgevoerd.**
- **Bla 1983-088 Trim systeem. Niet van toepassing op dit type.**
- **500 /1000 H inspection uitgevoerd .**
- **Forward heater inspectie en de test is uitgevoerd.**
- **LDG bearing block inspectie is uitgevoerd**
- **Oxygen bottle geïnspecteerd.**
- **Fuel quantity test is uitgevoerd.**

2**Technische administratie is overgenomen en is bij gewerkt door Authentic****3****A.D list is compleet en bijgewerkt.****4****Elevator trim rod end vervangen.
Text /opschriften zijn aangebracht.
Inspectie is volbracht.**

I certify that this Aircraft has been inspected in accordance to the CAA-NL, Easa regulations and Manufacturer guidelines and was determined to be in an airworthy condition.

Sign by:

Scoop of work

1000 hour inspection carried out acc maintenance manual and EASA guide lines.

- **ATA 12 Service. Airframe clean, lubrication and service. carried out.**
- **ATA 20 Standard practice. Engine Run's completed pre run failed test post run –satis-.**
- **ATA21 Air conditioning. Heater's inspection and operational check carried out. Hobs timer at 400 hours.**
- **ATA22 Auto pilot system inspected. Function test deferred to next flight.**
- **ATA23 Communication. ATC transponder mode C equipped, (VFR only).**
- **ATA24 Electrical power system check, Battery check & electrolyte level.**
- **ATA25 Equipment and furnishing. for safety, security, operation, date. Cleaned cabin, repaired several stitches on leader, installed new carpet.**
- **ATA27 Flight controls. Repair card 5; found tyre rubbing on rudder trim wheel, Rod end corroded tail trim tab.**
- **ATA28 Fuel. Fuel quantity check OAL 76-01/7, Fuel regulator shut off valve inspection AD 2004-25-16R1.**
- **ATA29 hydraulic system inspection and check.**
- **ATA30 De Icing. systems inspection and check for condition function. Repair card 9; Replaced circuit breaker**
- **ATA32 LDG. Repair card 7,10; Inspected nose steering attachment bolts, Repositioned RH brake hose to avoid hanging on nut, realigned LH outer door. Bearing block inspection carried out. Manual LDG system tested. –satis- .**
- **ATA33 Lights. Repair card 3; Replaced LDG light and repaired bracket.**
- **ATA35 oxygen. Inspected oxygen system and Bottle overhaul deferred to next 50 hours or September 2007.**
- **ATA72 Engine. Replaced air and oil filters, Engine mounts inspected, LH to be replaced at next 50 hours inspection or engine overhaul.**
- **ATA74 Ignition & starting; Repair card 1; rewired P leads and retimed magneto's.**
- **ATA79 Engine Oil, replaced Aero- shell W100.**